



101s5th.com

FLOOR PLANS

For more information, contact:

Doug Owen, SIOR Senior Vice President doug.owen@jll.com +1 502 394 2516


Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515



jll.com/louisville





For more information, contact:

Doug Owen, SIOR


Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM Vice President pat.richardson@jll.com

+1 502 394 2515







For more information, contact:

Doug Owen, SIOR


Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM Vice President

pat.richardson@jll.com +1 502 394 2515







For more information, contact:

Doug Owen, SIOR


Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM Vice President

pat.richardson@jll.com +1 502 394 2515







For more information, contact:

Doug Owen, SIOR


Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM Vice President pat.richardson@jll.com

+1 502 394 2515

()) JLL





For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516


Pat Richardson, CCIM Vice President

pat.richardson@jll.com +1 502 394 2515





14th Floor 5,182 SF | Suite 1420 2,603 SF | Suite 1410 7,785 SF Contiguous



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516


Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515



Disclaimer





For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516


Pat Richardson, CCIM Vice President

pat.richardson@jll.com +1 502 394 2515



T O W E R

16th Floor 1,135 SF | Suite 1635 2,032 SF | Suite 1640 3,222 SF Contiguous



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM


Vice President pat.richardson@jll.com +1 502 394 2515



Disclaimer



18th Floor 7,376 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516


Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515





22nd Floor 16,996 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515



Disclaimer



24th Floor 10,811 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM


Vice President pat.richardson@jll.com +1 502 394 2515



Disclaimer

T O W E R

28th Floor up to 7,882 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM


Vice President pat.richardson@jll.com +1 502 394 2515



Disclaimer



30th Floor 16,639 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515





31st Floor 5,433 SF



For more information, contact:

Doug Owen, SIOR


Senior Vice President doug.owen@jll.com +1 502 394 2516 **Pat Richardson, CCIM** Vice President pat.richardson@jll.com

+1 502 394 2515





32nd Floor 16,617 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516


Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515





36th Floor 7,996 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515





Annex - Retail up to 24,455 SF



For more information, contact:

Doug Owen, SIOR

Senior Vice President doug.owen@jll.com +1 502 394 2516

Pat Richardson, CCIM

Vice President pat.richardson@jll.com +1 502 394 2515



Disclaimer